This Contractor Announcement is applicable to MDOT trunkline construction contracts only.

Beginning with the bid letting on December 4, 2026, MDOT is providing this list of pay items that contain material costs for which compliance with the applicable domestic material requirements could not be verified based on the information available to MDOT. The identification of a pay item on this list does not mean that all materials or material costs associated with the pay item are non-compliant.

Table 1: Non-Compliant Domestic Materials

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
Section 406	Precast Culverts utilizing self-consolidating concrete	406C	Could not locate a compliant product
Section 602	Concrete Retrofit Load Transfer Products-Warranty Repair Work	602B	Could not locate a compliant product
7067001	Expansive Waterstop	USP	Could not locate a compliant product
7070120	Metal Mesh Panel	707C	Could not locate a compliant product
7070053	Steel Diaphragm, Prest Conc Beam, Furn and Fab	707G	Could not locate a compliant steel lock washers
8007050	Rack-Mtd Step-Down Transformer, __kV, Amp	USP	Could not locate a compliant transformer
8007050	Rack-Mtd Step-Up Transformer, __kV, Amp	USP	Could not locate a compliant transformer
8007050	Field Security Appliance	USP	Could not locate a compliant product
8007050	Subsurface Temperature Probe	USP	Could not locate a compliant product
8007050	Remote Processing Unit	USP	Could not locate a compliant product
8007050	Pavt Sensor, Non-Invasive Condition	USP	Could not locate a compliant product
8007050	Pavt Sensor, Invasive Condition	USP	Could not locate a compliant product
8007050	Pavt Sensor, Temperature	USP	Could not locate a compliant product
8007050	Atmospheric Sensor, Visibility	USP	Could not locate a compliant product
8007050	Atmospheric Sensor, Air Temperature/Relative Humidity	USP	Could not locate a compliant product
8007050	Atmospheric Sensor, Ultrasonic Wind	USP	Could not locate a compliant product
8007050	Atmospheric Sensor, Barometric Pressure	USP	Could not locate a compliant product
8007050	Atmospheric Sensor, Precipitation	USP	Could not locate a compliant product

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
8007050	Cellular Modem, 4G	USP	Antenna unlikely compliant
Section 808	Ornamental Aluminum Fence	USP	Could not locate a compliant product
Section 811	Permanent waterborne and regular dry pavement markings	811J	Could not locate a compliant product
8190301	Light Std Shaft, Install Salv	819C	Could not locate a compliant handhole frame.
8197050	Lighting Control Panel	USP	Could not locate a compliant product
8197050	Wood Pole, Fit Up, Metered Sec Elec Serv with Photo Control, Modified	USP	Could not locate a compliant product
8200070	Flsh Beacon, Controller and Cabinet, Solid State	820(O)	Polyphaser surge protection unlikely compliant
8200088	TS, Managed Field Ethernet Switch, Layer 2, Copper	820L	Switch is believed to be compliant, but misc. patch cord and hardware may not be
8200190	TS, One Way Span Wire Mtd	820	Span Wire Clamp unlikely compliant
8200193	TS, One Way Span Wire Mtd, LTGA	820	Span Wire Clamp unlikely compliant
8200195	TS, One Way Span Wire Mtd, RTGA	820	Span Wire Clamp unlikely compliant
8200197	TS, One Way Span Wire Mtd, STGA	820	Span Wire Clamp unlikely compliant
8200200	TS, Two Way Span Wire Mtd	820	Span Wire Clamp unlikely compliant
8200205	TS, Three Way Span Wire Mtd	820	Span Wire Clamp unlikely compliant
8200207	TS, Four Way Span Wire Mtd	820	Span Wire Clamp unlikely compliant
8200215	TS, 4th Level, LTGA	820	Span Wire Clamp unlikely compliant
8200217	TS, 4th Level, RTGA	820	Span Wire Clamp unlikely compliant
8200290	TS, One Way Span Wire Mtd, One Sect (LED)	820	Span Wire Clamp unlikely compliant
8200291	TS, Two Way Span Wire Mtd, One Sect (LED)	820	Span Wire Clamp unlikely compliant
8200292	TS, Three Way Span Wire Mtd, One Sect (LED)	820	Span Wire Clamp unlikely compliant

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
8200293	TS, Four Way Span Wire Mtd, One Sect (LED)	820	Span Wire Clamp unlikely compliant
8200301	TS, One Way Mast Arm Mtd, RTGA (LED)	820	Span Wire Clamp unlikely compliant
8200304	TS, One Way Mast Arm Mtd, FYA (LED)	820	Span Wire Clamp unlikely compliant
8200313	TS, One Way Span Wire Mtd (LED)	820	Span Wire Clamp unlikely compliant
8200314	TS, One Way Span Wire Mtd, FYA (LED)	820	Span Wire Clamp unlikely compliant
8200315	TS, One Way Span Wire Mtd, Five Sect (LED)	820	Span Wire Clamp unlikely compliant
8200316	TS, One Way Span Wire Mtd, LTGA (LED)	820	Span Wire Clamp unlikely compliant
8200318	TS, One Way Span Wire Mtd, RTGA (LED)	820	Span Wire Clamp unlikely compliant
8200320	TS, One Way Span Wire Mtd, STGA (LED)	820	Span Wire Clamp unlikely compliant
8200322	TS, Two Way Span Wire Mtd (LED)	820	Span Wire Clamp unlikely compliant
8200324	TS, Two Way Span Wire Mtd, Five Sect (LED)	820	Span Wire Clamp unlikely compliant
8200325	TS, Three Way Span Wire Mtd (LED)	820	Span Wire Clamp unlikely compliant
8200327	TS, Four Way Span Wire Mtd (LED)	820	Span Wire Clamp unlikely compliant
8200329	TS, 4th Level, LTGA (LED)	820	Span Wire Clamp unlikely compliant
8200331	TS, 4th Level, RTGA (LED)	820	Span Wire Clamp unlikely compliant
8200367	TS, Antenna	820	Polyphaser unlikely compliant
8200380	Video Traf Detection System	820T	All believed to be compliant except misc. connectors and cables
8200381	Video Traf Detection Camera	820T	All believed to be compliant except misc. connectors and cables
8200445	Hemispherical Video Detection System	820N	All believed to be compliant except misc. connectors and cables
8200490	Wireless Intercn, Sign Mtd Flasher, Master	820G	All believed to be compliant except misc. connectors and cables
8200491	Wireless Intercn, Sign Mtd Flasher, Repeater	820G	All believed to be compliant except misc. connectors and cables

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
8200493	Wireless Intercn, Sign Mtd Flasher, Solar Power, Master	820G	All believed to be compliant except misc. connectors and cables
8200494	Wireless Intercn, Sign Mtd Flasher, Solar Power, Repeater	820G	All believed to be compliant except misc. connectors and cables
8200498	Cellular Modem, TS, 4th G	820B	Antenna unlikely compliant
8200500	TS Uninterruptible Power System	820HH	Conditioner unlikely compliant
8200529	Radar Vehicle Detection Radius System	820X	All believed to be compliant except misc. connectors and cables
8200530	Radar Vehicle Detection Radius, Stop Bar Sensor	820X	All believed to be compliant except misc. connectors and cables
8200531	Radar Vehicle Detection Radius, Stop Bar Advance Sensor	820X	All believed to be compliant except misc. connectors and cables
8200532	Multi-Sensor Vehicle Detection System	820LL	All believed to be compliant except misc. connectors and cables
8200535	Multi-Sensor Vehicle Detection Sensor	820LL	All believed to be compliant except misc. connectors and cables
8202275	TS, One Way Span Wire Mtd, One Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202278	TS, Two Way Span Wire Mtd, One Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202281	TS, Three Way Span Wire Mtd, One Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202284	TS, Four Way Span Wire Mtd, One Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202287	TS, One Way Span Wire Mtd (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202290	TS, Two Way Span Wire Mtd (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202293	TS, Three Way Span Wire Mtd (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202296	TS, Four Way Span Wire Mtd (LED), Long Life	820KK	Span Wire Clamp unlikely compliant

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
8202299	TS, One Way Span Wire Mtd, FYA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202302	TS, Two Way Span Wire Mtd, FYA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202305	TS, FourWay Span Wire Mtd, FYA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202308	TS, One Way Span Wire Mtd, Five Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202311	TS, Two Way Span Wire Mtd, Five Sect (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202314	TS, One Way Span Wire Mtd, LTGA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202317	TS, One Way Span Wire Mtd, RTGA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202320	TS, One Way Span Wire Mtd, STGA (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202323	TS, One Way Span Wire Mtd, 4th Level (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202326	TS, Two Way Span Wire Mtd, 4th Level (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202329	TS, Three Way Span Wire Mtd, 4th Level (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8202332	TS, Four Way Span Wire Mtd, 4th Level (LED), Long Life	820KK	Span Wire Clamp unlikely compliant
8200050	Global Positioning System Module	820K	Not Compliant
8200247	TS, Lens	USP	Not Compliant
8260157	Surveillance System, Remote Site, Type A	826	Could not locate a compliant camera
8260158	Surveillance System, Remote Site, Type B	826	Could not locate a compliant camera

Pay Item	Pay Item Description	FUSP Series	Compliance Notes
8260159	Surveillance System, Remote Site, Type C	826	Could not locate a compliant camera
8260080	Managed Field Ethernet Switch, Layer 2	826D	Could not locate a compliant switch, power supply, or miscellaneous components
8260082	Managed Field Ethernet Switch, Layer 3	826D	Could not locate a compliant switch, power supply, or miscellaneous components
8260065	Fiber Optic, Hardware Assembly, Small	826C	Could not locate a compliant assembly
8260066	Fiber Optic, Hardware Assembly, Medium	826C	Could not locate a compliant assembly
8260067	Fiber Optic, Hardware Assembly, Large	826C	Could not locate a compliant assembly
8260071	Fiber Optic, Pigtail	826C	Could not locate compliant pigtail or components
8260072	Fiber Optic, Jumper	826C	Could not locate compliant jumper or components

MDOT used available vendors, manufacturers, and online information to evaluate domestic material compliance. In some cases, sufficient information was not available to verify compliance. Based on the information available at the time, MDOT was unable to verify domestic material compliance for certain material costs within the pay items listed above. The list identifies pay items where compliance could not be verified and does not indicate that the entire pay item, or all materials included in the pay item, are non-compliant.

Unique Special Provisions should be reviewed carefully by the contractor for domestic material compliance.

Materials or pay items not included on this list should not be assumed to be domestic material compliant without verification by the Contractor. MDOT is providing this list solely for Contractors' convenience; Contractors should not rely on this list as evidence of domestic material compliance or noncompliance for any pay item. Contractors remain responsible for verifying the domestic material compliance of all materials proposed for use on their projects, as contract requirements, product availability, manufacturing processes, and industry practices may change over time.

Contractors should independently review the project proposal, plans, applicable contract specifications, and domestic material requirements when selecting materials and determining the documentation necessary to demonstrate compliance.