

NOTE:
Porcelain strain insulator (if required) shall meet the codes and placement requirements of the local utility co.

SERVICE DISCONNECT

NOTE:
Only 1-2" hole in steel pole allowed for mounting disconnect.

METERED SERVICE WITH 1-3/C #6 AWG SERVICE CABLE

METERED SERVICE WITH 3-1/C #6 AWG SERVICE CABLE

NOT TO SCALE

File: RefDoc/TR/Signals/Web/Sp Det/Fin/SIG201A.dgn Rev. 02/16/17

MDOT Michigan Department of Transportation PREPARED BY TRAFFIC AND SAFETY DRAWN BY: DJF CHECKED BY:	ENGINEER OF DELIVERY ENGINEER OF DEVELOPMENT (SPECIAL DETAIL) FHWA APPROVAL DATE	MICHIGAN DEPARTMENT OF TRANSPORTATION BUREAU OF HIGHWAYS DELIVERY STANDARD PLAN FOR SECONDARY SERVICE/DISCONNECT FOR STEEL POLES PLAN DATE: SIG-201-A SHEET 1 of 2



NON-METERED SERVICE WITH 1-3/C #6 AWG SERVICE CABLE

NON-METERED SERVICE WITH 3-1/C #6 AWG SERVICE CABLE

NOT TO SCALE

MICHIGAN DEPARTMENT OF TRANSPORTATION BUREAU OF HIGHWAYS DELIVERY STANDARD PLAN	(SPECIAL DETAIL) FHWA APPROVAL DATE	PLAN DATE	SIG-201-A SHEET 2 of 2

File: RefDoc/TR/Signals/Web/Sp Det/Fin/SIG201A.dgn Rev. 02/16/17

AS-LET PLAN REVISIONS											
NO.	DATE	AUTH	DESCRIPTION	NO.	DATE	AUTH	DESCRIPTION	MDOT Michigan Department of Transportation	DATE:	CS:	DRAWING / SHEET
									DESIGN UNIT:	JN:	
									FILE:	TSC:	