


SIGHT ORIENTATION DIAGRAM




SIDE POLE MOUNTED

BRACKET TRUSS ARM MOUNTED


- (*) Notes: 1. Use $3/8" \times 5"$ Hex head screw (2" min.) for mounting to wood poles. 2. Use $3/4" \times 0.30$ min. stainless steel band for mounting to steel poles. pedistals or bracket truss arms.

NOT TO SCALE

MICHIGAN DEPARTMENT OF TRANSPORTATION BUREAU OF HIGHWAYS DELIVERY STANDARD PLAN	(SPECIAL DETAIL) FHWA APPROVAL DATE		SIG-110-1	SHEET
File: RefDoc/TR/Signals/Web/Sp Det/Fin/SIG440A.dgn Rev. 02/16/17		PLAN DATE	310 440 A	2 of 4



VERTICAL ORIENTATION



HORIZONTAL ORIENTATION

MICROWAVE VEHICLE SENSOR ORIENTATION DIAGRAM

NUT	ΙU	SCALE	

MICHIGAN DEPARTMENT OF TRANSPORTATION BUREAU OF HIGHWAYS DELIVERY STANDARD PLAN	(SPECIAL DETAIL) FHWA APPROVAL DATE		SIG-440-A	SHEET
File: RefDoc/TR/Signals/Web/Sp Det/Fin/SIG440A.dgn Rev. 02/16/17			310 440 A	3 of 4

