

Aggregate Source Inventory Database



PIT NAME				02-0090SG	
Peterson Pond					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Sand & Gravel Quarry		2009		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				No Data
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS			LAST PRODUCER ON RECORD		
5370 Rielly Lake Road, Rapid River, MI 49878			Wells Contracting/Crushing And Screening		

Revised: Friday, February 24, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

02-090 Historical