## Aggregate Source Inventory Database



					Michigan Department of Transportation
PIT NAME  Hersha					15-0047SG
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Sand & Gravel Quarry			1977		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				LA Abrasion results expire 5 years from reported date for this source
	В	НМА	32	7/24/2019	
	С				
	D				
	Е				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRES				LAST PRODUCER ON RECORD	

3437 6 Mile Lake Road, Ellsworth, MI 49729

**Team Elmers** 

Revised: Monday, February 27, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control