

Aggregate Source Inventory Database



PIT NAME					15-0047SG
Hersha					
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Sand & Gravel Quarry			1977		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				LA Abrasion results expire 5 years from reported date for this source *Generic Classification
	B		30	04/24/2024	
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS					LAST PRODUCER ON RECORD
3437 6 Mile Lake Road, Ellsworth, MI 49729					Elmer's Crane and Dozer, Inc.

Revised: Wednesday, April 24, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

15-047 Historical