

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>17-0093CA</b>	
<b>Rockview</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Carbonate Quarry		2002		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
<b>Test</b>	<b>Grade</b>	<b>Material</b>	<b>Result</b>	<b>Date</b>	<b>NOTES</b>
<b>L.A. ABRASION (MTM 102)</b>	A				No Data
	B				
	C				
	D				
	E				
	F				
<b>A.W.I. (MTM 112)</b>	<b>Wear Track Value</b>		269	10/18/2018	Wear Track results expire 5 years from reported date
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
29111 Meridian Road, Messel, MI 49774			Payne & Dolan, Inc.		

Revised: Tuesday, February 28, 2023

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**

**17-093 Historical**