

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>YD-0041</b>	
<b>Project Temporary 23061-115095 Stockpile #2</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Crushed Concrete Yard		3/24/2021		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
Test	Grade	Material	Result	Date	NOTES
<b>L.A. ABRASION (MTM 102)</b>	<b>A</b>				LA Abrasion results expire 1 year from reported date for this source
	<b>B</b>	21AA	32	3/29/2023	
	<b>C</b>				
	<b>D</b>				
	<b>E</b>				
	<b>F</b>				
<b>A.W.I. (MTM 112)</b>	<b>Wear Track Value</b>				No Data
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
Kalin - I96 and Cochran Road Interchange			Kalin Construction Company Inc.		

Revised: Thursday, May 11, 2023

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**