

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>YD-0047</b>	
<b>Red Arrow Plant</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Crushed Concrete Yard		2008		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
<b>Test</b>	<b>Grade</b>	<b>Material</b>	<b>Result</b>	<b>Date</b>	<b>NOTES</b>
<b>L.A. ABRASION (MTM 102)</b>	<b>A</b>	21AA	32	06/23/2023	Results from this source expire 1 year from reported date
	<b>B</b>				
	<b>C</b>				
	<b>D</b>				
	<b>E</b>				
	<b>F</b>				
<b>A.W.I. (MTM 112)</b>	<b>Wear Track Value</b>				No Data
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
2374 Red Arrow Road, Burton, MI 48529			Zito Construction		

Revised: Friday, June 23, 2023  
**25-037 Historical**

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**