Aggregate Source Inventory Database					<b>CALIDOT</b> Michigan Department of Transportation
PIT NAME					31-0087IM
Valley View					31-000/1101
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Igneous/Metamorphic Quarry			2005		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				
	В	6A	18	8/5/2021	LA Abrasion results expire 5 years from reported date for this source
	С		21	6/14/2023	
	D				
	E				
	F				
FREEZE-THAW TESTING (MTM 113, 114, 115)	Expansion				
	Crush				
	SG (OD)				
	Deletrious				
A.W.I. (MTM 112)	Wear Track Value		435	10/18/2018	Wear Track results expire 5 years from reported date
ADDRESS					LAST PRODUCER ON RECORD
46425 Green Acre Road, Houghton, MI 49931					Mottes Const.
Revised: Wednesday, June 14, 2023 NOTE: 31-087 Historical					If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control