

Aggregate Source Inventory Database



PIT NAME				36-0074SG	
Paint River Road					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Sand & Gravel Quarry		2010		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				No Data
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS			LAST PRODUCER ON RECORD		
134 Paint River Road, Crystal Falls Township, MI 49920			Bacco Construction Company		

Revised: Friday, March 3, 2023

36-074 Historical

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control