## **Aggregate Source Inventory Database**



					Michigan Department of Transportation
PIT NAME Split Rock Quarry					36-0078IG
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Igneous & Metamorphic Quarry			1/5/2023		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				LA Abrasion results expire 5 years from reported date for this source
	В				
	С	НМА	14	4/4/2023	
	D				
	Е				
	F				
A.W.I. (MTM 112)	Wear Track Value		323	4/22/2016	Result extended, until new testing is complete
ADDRESS					LAST PRODUCER ON RECORD
Co Road 424, Crystal Falls,MI 49920					Bacco Construction Company

Revised: Tuesday, April 4, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control