Aggregate Source Inventory Database



| | | | | | Michigan Department of Transportation |
|---|------------------|----------|-------------------|-------------------------|---|
| PIT NAME Round Lake West | | | | | 46-0052SG |
| DEPOSIT TYPE | | | ADDED TO DATABASE | | STATUS: INACTIVE/ACTIVE/URBANIZED |
| Sand & Gravel Quarry | | | 2010 | | ACTIVE |
| AGGREGATE QUALITY TESTING RESULTS | | | | | |
| Test | Grade | Material | Result | Date | NOTES |
| L.A. ABRASION (MTM 102) | Α | | | | LA Abrasion results expire 5 years from reported date for this source |
| | В | 21AA | 29 | 09/28/2023 | |
| | С | | | | |
| | D | | | | |
| | Е | | | | |
| | F | | | | |
| A.W.I. (MTM 112) | Petrographic AWI | | | | See MDOT Nomograph |
| ADDRES | | | | LAST PRODUCER ON RECORD | |
| approx 9964 Round Lake Hwy, Addison, MI 49220 | | | | | Gerken Materials Inc |

Revised: Thursday, September 28, 2023

46-052 Historical

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control