

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>52-0107SG</b>	
<b>North Lake #2</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Sand & Gravel Quarry		2011		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
Test	Grade	Material	Result	Date	NOTES
<b>L.A. ABRASION (MTM 102)</b>	<b>A</b>				No Data
	<b>B</b>				
	<b>C</b>				
	<b>D</b>				
	<b>E</b>				
	<b>F</b>				
<b>A.W.I. (MTM 112)</b>	<b>Petrographic AWI</b>				Contact Aggregate Quality
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
5976 Diorite Road, Ely Township, MI 49849			Payne & Dolan, Inc.		

Revised: Monday, March 6, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

**52-107 Historical**