Aggregate Source Inventory Database



| | | | Michigan Department of Transportation | | |
|-----------------------------------|-----------|----------|---------------------------------------|-------------------------|---|
| PIT NAME Tyler Road | | | | | 54-0069SG |
| DEPOSIT TYPE | | | ADDED TO DATABASE | | STATUS: INACTIVE/ACTIVE/URBANIZED |
| Sand & Gravel Quarry | | | 2005 | | ACTIVE |
| AGGREGATE QUALITY TESTING RESULTS | | | | | |
| Test | Grade | Material | Result | Date | NOTES |
| L.A. ABRASION (MTM 102) | Α | | | | LA Abrasion results expire 5 years from reported date for this source |
| | В | 23A | 26 | 5/23/2023 | |
| | С | 34R | 20 | 5/23/2023 | |
| | D | | | | |
| | Е | | | | |
| | F | | | | |
| A.W.I. (MTM 112) | Petrograp | hic AWI | | | Contact Aggregate Quality |
| ADDRES | | | | LAST PRODUCER ON RECORD | |
| | | | | | |

Revised: Tuesday, May 23, 2023

23242 Tyler Road, Morley, MI 49346

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

J R Aggregates

54-069 Historical