

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>63-0125SG</b>	
<b>Dixie Hwy Pit</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Sand & Gravel Quarry		2017		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
<b>Test</b>	<b>Grade</b>	<b>Material</b>	<b>Result</b>	<b>Date</b>	<b>NOTES</b>
<b>L.A. ABRASION (MTM 102)</b>	A				No Data
	B				
	C				
	D				
	E				
	F				
<b>A.W.I. (MTM 112)</b>	<b>Petrographic AWI</b>				Contact Aggregate Quality
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
6728 Belford Road, Holly, MI 48442			Zito Construction Co		

Revised: Tuesday, March 7, 2023

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**

**63-125 Historical**