

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>YD-0127</b>	
<b>Adams Recycle</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Crushed Concrete Yard		2010		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
<b>Test</b>	<b>Grade</b>	<b>Material</b>	<b>Result</b>	<b>Date</b>	<b>NOTES</b>
<b>L.A. ABRASION (MTM 102)</b>	<b>A</b>				No Data
	<b>B</b>				
	<b>C</b>				
	<b>D</b>				
	<b>E</b>				
	<b>F</b>				
<b>A.W.I. (MTM 112)</b>	<b>Wear Track Value</b>				No Data
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
8770 N Oceana Drive, Pentwater, MI 49449			Ken Adams		

Revised: Tuesday, March 7, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

**64-059 Historical**