Aggregate Source Inventory Database					<b>EXAMPLE</b> A Second Seco
PIT NAME					
J & N Excavating - Gaylord Yard					YD-0174
DEPOSIT TYPE			ADDED TO DATABAS		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			9/3/2021		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				No Data
	В				
	С				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Trac	k Value			No Data
ADDRES				LAST PRODUCER ON RECORD	
1223 Anna Dr., Gaylord, MI 49735					J & N Excavating
Revised: Tuesday, March 7, 2023				NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control	

**69-053CC Historical**