Aggregate Source Inventory Database					A CALIFICATION Michigan Department of Transportation
PIT NAME					71-0069SG
Tedrock					71-000338
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Sand & Gravel Quarry			11/30/2021		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				LA Abrasion results expire 5 years from reported date for this source
	В	HMA	22	12/1/2021	
	С				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRES				LAST PRODUCER ON RECORD	
13935 Melvell Road	49776			Alpena Aggregate Inc	
	rch 7, 2023		NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control		

71-069 Historical