

Aggregate Source Inventory Database



PIT NAME				YD-0161	
Mid-Michigan Crushing & Recycling Ecorse Yard					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		6/17/2021		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A	21AA	38	05/27/2022	LA Abrasion results expire 1 year from reported date for this source
	B	21AA	34	04/20/2023	
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
28233 Ecorse, Romulus, MI 48174			Mid-Michigan Crushing & Recycling		

Revised: Thursday, April 20, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

82-036 Historical