

Aggregate Source Inventory Database



PIT NAME				YD-0199	
Mid-Michigan Crushing & Recycling Taylor Yard					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		8/8/2022		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A	4G	35	9/21/2022	LA Abrasion results expire 1 year from reported date for this source
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
20538 Pennsylvania Road, Taylor, MI 48180			Mid-Michigan Crushing & Recycling		

Revised: Thursday, March 9, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

82-038CC Historical