

Aggregate Source Inventory Database



PIT NAME				YD-0183	
Ann Arbor Road Yard					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		11/9/2022		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A		30	03/29/2023	LA Abrasion results expire 1 year from reported date for this source
	B	OGDC	31	04/04/2022	
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
Crusher Plant located at the ramp from Ann Arbor Road to Southbound I-275			Great Lakes Aggregate Co.		

Revised: Wednesday, March 29, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

82-810 Historical