

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>92-0051CA</b>	
<b>South Lake Stone</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Carbonate Quarry		2016		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
Test	Grade	Material	Result	Date	NOTES
<b>L.A. ABRASION (MTM 102)</b>	A				LA Abrasion results expire 5 years from reported date for this source
	B	6AA	26	10/6/2021	
	C				
	D				
	E				
	F				
<b>FREEZE-THAW TESTING (MTM 113, 114, 115)</b>	Expansion		0.011	3/23/2022	6AA tested, expires 3/22/2027  <i>The 6 series for FT is the standard and covers ALL gradations, while the 17 series result is valid for 17 series gradations only</i>
	Crush		100		
	SG (OD)		2.69		
	Deleterious		as tested (soft 0.7%, chert 0.1% - sum of soft and chert 0.8%)		
<b>A.W.I. (MTM 112)</b>	Wear Track Value		261	8/15/2017	Wear Track result has been extended, pending new test
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
18900 Clay St., Hebron, IN 46341			Rieth Riley Construction Company Inc.		

Revised: 

---

Friday, March 10, 2023

## **92-051 Historical**

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**