

Aggregate Source Inventory Database



PIT NAME				92-0052SG	
Angola					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Sand & Gravel Quarry		2017		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				No Data
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS			LAST PRODUCER ON RECORD		
225 South 600 West, Angola, IN 46703			Clifford Aggregate Inc		

Revised: Friday, March 10, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

92-052 Historical