

Aggregate Source Inventory Database



PIT NAME				93-0040SF	
Fulton Mill Service					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Steel Furnace Slag		1999		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				LA Abrasion results expire 5 years from reported date for this source
	B		15	11/23/2021	
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value		408	11/14/2022	Wear track result expires 5 years from reported date
ADDRESS			LAST PRODUCER ON RECORD		
6565 Co Rd, Delta, OH 43515			E.C. Levy		

Revised: Friday, March 10, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

93-040 Historical