

Aggregate Source Inventory Database



PIT NAME					93-0057SG
United Aggregate					
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Sand & Gravel Quarry			12/8/2022		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				LA Abrasion results expire 5 years from reported date for this source
	B		28	1/19/2023	
	C				
	D				
	E				
	F				
FREEZE-THAW TESTING (MTM 113, 114, 115)	Expansion				
	Crush				
	SG (OD)				
	Deleterious		as tested (soft 7.9%, chert 3.1% - sum of Deleterious 11.0%)		
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS					LAST PRODUCER ON RECORD
16364 Millersburg Road, Danville, OH 43014					

Revised: Friday, March 10, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

93-057 Historical