Aggregate Source Inventory Database					CALIDOT Michigan Department of Transportation
PIT NAME					94-0035SG
Crooked Lake				37-003330	
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Sand & Gravel Quarry			1999		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				LA Abrasion results expire 5 years from reported date for this source
	В	22A	18	8/11/2020	
	С				
	D				
	E				
	F				
A.W.I. (MTM 112)	Petrographic AWI				Contact Aggregate Quality
ADDRESS				LAST PRODUCER ON RECORD	
64450 Crooked Lake Road, Onalaska, WI 54650					Milestone Materials
Revised: Friday , March 10, 2023 94-035 Historical				NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control	