

Aggregate Source Inventory Database



| PIT NAME | | | | YD-0003 | |
|---|-------------------------|--------------------------|---------------------------------|--|---------|
| Project Temporary 03035-101615A | | | | | |
| DEPOSIT TYPE | | ADDED TO DATABASE | | STATUS: INACTIVE/ACTIVE/URBANIZED | |
| Crushed Concrete Yard | | 4/16/2021 | | ACTIVE | |
| AGGREGATE QUALITY TESTING RESULTS | | | | | |
| Test | Grade | Material | Result | Date | NOTES |
| L.A. ABRASION (MTM 102) | A | | | | No Data |
| | B | | | | |
| | C | | | | |
| | D | | | | |
| | E | | | | |
| | F | | | | |
| A.W.I. (MTM 112) | Wear Track Value | | | | No Data |
| ADDRESS | | | LAST PRODUCER ON RECORD | | |
| median of I-196 in Saugatuck Township, Saugatuck, Michigan 49453 | | | Kalin Construction Company Inc. | | |

Revised: Tuesday, July 9, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

03-801 Historical