

Aggregate Source Inventory Database



PIT NAME				YD-0244	
Salzburg Yard					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		6/27/2024		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A	21AA	36	7/9/2024	LA Abrasion results expire 1 year from reported date for this source
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
Flajola Rd, Freedland, Michigan			Kalin Construction Company Inc.		

Revised: Tuesday, July 9, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control