

Aggregate Source Inventory Database



PIT NAME				YD-0047	
Red Arrow Plant					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		2008		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A	21AA	31	05/01/2024	Results from this source expire 1 year from reported date
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
2374 Red Arrow Road, Burton, MI 48529			Zito Construction		

Revised: Thursday, July 11, 2024

25-037 Historical

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control