Aggregate Source Inventory Database



					Michigan Department of Transportation
PIT NAME Project Temporary 32022-119065					YD-0054
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			2020		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				No Data
	В				
	С				
	D				
	Е				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS				LAST PRODUCER ON RECORD	
1838 Thompson Road, Bad Axe, MI 48413				Kalin Construction Company, Inc.	

Revised: Thursday, July 11, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

32-800 Historical