Aggregate Source Inventory Database



rigging and minorition of parameter					Michigan Department of Transportation
PIT NAME					YD-0176
Project Temporary 38101-129153A					10-0170
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			9/20/2021		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				No Data
	В				
	С				
	D				
	Е				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS					LAST PRODUCER ON RECORD
2373 Cooper Street, Jackson, MI 49201					Great Lakes Aggregate Co.

Revised: Thursday, July 11, 2024

38-807 Historical

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control