

Aggregate Source Inventory Database



PIT NAME				YD-0077	
Hillside Gravel Crushed Concrete Yard					
DEPOSIT TYPE		ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED	
Crushed Concrete Yard		2014		ACTIVE	
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				No Data
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS			LAST PRODUCER ON RECORD		
2702 Ravine Road, Kalamazoo, MI 49004			Balkema Excavating		

Revised: Friday, July 12, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

39-082CC Historical