Aggregate Source Inventory Database



Michigan Department of Transportation					
PIT NAME Project Temporary 105885A					YD-0081
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			5/18/2021		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α				No Data
	В				
	С				
	D				
	Е				
	F				
A.W.I. (MTM 112)	Wear Trac	k Value			No Data
ADDRESS				LAST PRODUCER ON RECORD	
Cork Street, Kalamazoo, Michigan 49001				Kalin Construction Company Inc.	

Revised: Friday, July 12, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

39-802 Historical