Aggregate Source Inventory Database



					Michigan Department of Transportation
PIT NAME Round Lake West Yard					YD-0096
Noulla Lake West Tala					
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			2010		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
	Α				
L.A. ABRASION (MTM 102)	В				No Data
	С				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRES				LAST PRODUCER ON RECORD	

approx 9964 Round Lake Hwy, Addison, MI 49220

Gerken Materials Inc

Revised: Friday, July 12, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

46-052 Historical