

Aggregate Source Inventory Database



PIT NAME					YD-0103
Fiore Crushed Concrete Mound Road					
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard			2002		ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	A				No Data
	B				
	C				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRESS					LAST PRODUCER ON RECORD
33200 Mound Road, Streling Heights, MI 48310					Fiore Crushed Concrete

Revised: Friday, July 12, 2024

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

50-052 Historical