Aggregate Source Inventory Database



					Michigan Department of Transportation
PIT NAME					77-TP-0013
Parmar Port Huron					11-11-0013
DEPOSIT TYPE			ADDED TO DATABASE		STATUS: INACTIVE/ACTIVE/URBANIZED
Crushed Concrete Yard					ACTIVE
AGGREGATE QUALITY TESTING RESULTS					
Test	Grade	Material	Result	Date	NOTES
L.A. ABRASION (MTM 102)	Α	4G	33	9/8/2025	LA Abrasion results expire 1 year from reported date for this source
	В				
	С				
	D				
	E				
	F				
A.W.I. (MTM 112)	Wear Track Value				No Data
ADDRES				LAST PRODUCER ON RECORD	
Project Speciifc, Port Huron, MI					

Revised: Monday, September 8, 2025

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control