

Aggregate Source Inventory Database



| | | | | | |
|--|-------------------------|------------------------|--------------------------------|--|--------------|
| PIT NAME | | | | YD-0146 | |
| Project Temporary 210066-44044 | | | | | |
| DEPOSIT TYPE | | ADDED TO DATABA | | STATUS: INACTIVE/ACTIVE/URBANIZED | |
| Crushed Concrete Yard | | 7/13/2021 | | ACTIVE | |
| AGGREGATE QUALITY TESTING RESULTS | | | | | |
| Test | Grade | Material | Result | Date | NOTES |
| L.A. ABRASION (MTM 102) | A | | | | No Data |
| | B | | | | |
| | C | | | | |
| | D | | | | |
| | E | | | | |
| | F | | | | |
| A.W.I. (MTM 112) | Wear Track Value | | | | No Data |
| ADDRESS | | | LAST PRODUCER ON RECORD | | |
| Lippmann Location | | | Great Lakes Aggregate Co. | | |

Revised: Thursday, March 9, 2023

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control

77-801 Historical