

# Aggregate Source Inventory Database



<b>PIT NAME</b>				<b>YD-0183</b>	
<b>Ann Arbor Road Yard</b>					
<b>DEPOSIT TYPE</b>		<b>ADDED TO DATABASE</b>		<b>STATUS: INACTIVE/ACTIVE/URBANIZED</b>	
Crushed Concrete Yard		11/9/2022		ACTIVE	
<b>AGGREGATE QUALITY TESTING RESULTS</b>					
<b>Test</b>	<b>Grade</b>	<b>Material</b>	<b>Result</b>	<b>Date</b>	<b>NOTES</b>
<b>L.A. ABRASION (MTM 102)</b>	A				No Data
	B				
	C				
	D				
	E				
	F				
<b>A.W.I. (MTM 112)</b>	<b>Wear Track Value</b>				No Data
<b>ADDRESS</b>			<b>LAST PRODUCER ON RECORD</b>		
Crusher Plant ramp from Ann Arbor Road to Southbound I-275			Great Lakes Aggregate Co.		

Revised: Tuesday, July 16, 2024

**NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control**

**82-810 Historical**