

Aggregate Source Inventory Database



| | |
|---|---------------------|
| PIT NAME | <h1>82-YD-0293</h1> |
| Project Temporary 210679, 213488 | |

| | | |
|-----------------------|--------------------------|--|
| DEPOSIT TYPE | ADDED TO DATABASE | STATUS: INACTIVE/ACTIVE/URBANIZED |
| Crushed Concrete Yard | 1/1/2026 | ACTIVE |

AGGREGATE QUALITY TESTING RESULTS

| Test | Grade | Material | Result | Date | NOTES |
|------------------------------------|-------------------------|----------|--------|-----------|--|
| L.A. ABRASION (MTM 102) | A | 21AA | 41 | 5/27/2026 | LA Abrasion results expire 1 year from reported date for this source |
| | B | | | | |
| | C | | | | |
| | D | | | | |
| | E | | | | |
| | F | | | | |
| A.W.I. (MTM 112) | Wear Track Value | | | | No Data |

| | |
|----------------|--------------------------------|
| ADDRESS | LAST PRODUCER ON RECORD |
|----------------|--------------------------------|

| |
|-----------------|
| Great Lakes Agg |
|-----------------|

Revised: Monday, June 1, 2026

NOTE: If you have updates for this pit (ex. Status, producer, or an increase in area for legal description) please contact Aggregate Quality Control